



USER MANUAL

LINE S5470(F) LINE S3360 LINE S4067

Please read the manual carefully before installation and application, and use the product in the correct way. Instructions on accessories are included in the manual.

Please properly maintain the manual after reading and understanding it for convenient reference by all users of the product in the future.

ISO Doc. No.: SM-OPN-QSF12

www.switch-made.com






CONTENTS

Components	01
Installation	
Surface-mounted	02
Pendant	05
Recessed	09
Wall-mounted	13
Cutting	17
	Pendant Recessed





Essentials

- ① Profile x 1
- 2 End caps x 2
- 3 Flexible Diffuser x 1 4 Carrier clip x 4
- 5 Surface-mounted screws x 3
- 6 Cable clip

Connectors *

7) 180° extender

Light source and power supply *

- 8 Flexible strip / rigid modular
- 9 Power supply

Installation accessories *

- 10 Pendant accessories with junction box / pedant accessories
- (11) Recessed accessories without trim
- 12 Wall-mounted accessories

^{*} Optional accessories






Installation


Surface-mounted 2.5 m






























































Pendant 2.5 m















































































Recessed 2.5 m





























b: Connect the rigid modular to pins correctly (do not confuse the anode with cathode), and then slide the rigid modular into the carrier












































Wall-mounted 2.5 m




























































Cutting



Mark the cutting length (The cutting length should be times the length of minimum cutting unit, and profile loss will occur during cutting by about the thickness of the blade), and please make reservation of profile length

Cutting point

Multiple of the minimum cutting unit of the strip

Loss

2500

